

FIGURE 1






Figure 2




PREHEAT 400-410 F DEGREES 4 MINUTES SUBLIMATE 400-410 F DEGREES 10 SECONDS 400 PRESSURE



PREHEAT 400-410 F DEGREES 4 MINUTES SUBLIMATE 400-410 F DEGREES 8 SECONDS 400 PRESSURE



PREHEAT 400-410 F DEGREES 4 MINUTES SUBLIMATE 400-410 F DEGREES 6 SECONDS 400 PRESSURE



PREHEAT 400-410 F DEGREES 4 MINUTES SUBLIMATE 400-410 F DEGREES 4 SECONDS 400 PRESSURE

FIGURE 3

Double-Heat Press




FIGURE 4



FOUNTAINHEAD BY NEVAMAR
PREHEAT @ 400 F DEGREES 45# PRESSURE
4 MINUTES

SUBLIMATE @ 400 F DEGREES 45# 45 SECONDS
EXCELLENT BLACK & COLOR & DETAIL



#1 & #2 WILSONART GIBALTAR
DESIGNER WHITE
PRE-HEAT @ 400 F DEGREES 45# PRESSURE
4 MINUTES

SUBLIMATE 400 F DEGREES 45 # 45 SECONDS

IMAGE SUBLIMATED EXCELLENT GOOD BLACKS
GOOD COLOR GOOD DETAIL

RESULTS EXCELLENT GOOD FOR PRODUCT

C

FIGURE 5

